

General Environmental Incident Summary

Incident: 4188 **Date/Time Notice:** 8/5/2016 1330 **DEM Incident No:**
Responsible Party: Headwaters Resources
Date Incident: 7/25/2016 **Time Incident:** 1345 **Duration:** 30 minutes
County: McLean **Twp:** 146 **Rng:** 82 **Sec:** 21 **Qtr:** NW NW NW
Lat: 47.45647 **Long:** -101.13710 **Method:** Interpolation from map
Location Description: Headwaters Resources, 2843 3rd ST SW Underwood, ND 58576---7 miles NW of facility in section 26 pit
Submitted By: Ron Sutter **Affiliation:** Headwaters
Address: 2843 3rd St. SW
City: Underwood **State:** ND **Zip:** 58576

Received By:

Contact Person: Ron Sutter
2843 3rd ST SW
Underwood, ND 58576

Distance Nearest Occupied Building: 1 Miles **Release Contained:** Yes

Type of Incident: Vehicle Accident

Description of Released Contaminant: fly ash from the coal creek generatoning station

Volume Spilled: 80000.00 pounds **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

narrow haul road empty truck did not pull over far enough causing loaded truck to put tires on soft shoulder and tip on passengers side

Risk Evaluation:

inhalation of fly ash may cause respiratory irritation

of Fatalities: 0 **# of Injuries:** 1 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

no potential impacts to soil/water expected as all visible traces of the release were cleaned up immediately.

Action Taken or Planned:

cleaned spill with loader and placed in pit where incident occurred(incident and spill in same pit where ash is located) future plans to have empty trucks give loaded trucks more room

Wastes Disposal Location: in same pit incident occurred

Agencies Involved:

Updates

Date: 8/9/2016 **Status:** Reviewed - Assigned to NDDoH Division **Author:** O'Gorman, Brian

Updated Volume:

Notes:

Assigned to Diana Trussell of NDDoH Division of Waste Management for further follow-up.

Date: 11/28/2016 **Status:** Reviewed - Assigned to NDDoH Division **Author:** O'Gorman, Brian

Updated Volume:

Notes:

Received an email from Diana Trussell of NDDoH Division of Waste Management that contained a photo of the area where the ash waste was spilled. Email and photo added to incident folder.

Date: 11/28/2016 **Status:** Reviewed - Follow-up Required **Author:** Souder, Taylor

Updated Volume:

Notes:

Further follow-up needed.